



**PIONEER  
PARTNER**



# SERVICE BULLETIN

Bulletin No. 7  
Section No. 8

## SUBJECT: IGNITION SYSTEM CHANGE


MODEL: P39

SERIAL: 612 524 738

We have **discontinued** the use of the **Wico ignition system** on the P39 and have equipped current units with the **Phelon system** used on models P42, P52 & P62.

Parts which are now changed include the module, flywheel and switch wire. **Please make sure** you order the correct replacement parts.

OLD STYLE



NEW STYLE

