



**PIONEER
PARTNER®**



SERVICE BULLETIN

August, 1986

Section No. 7
Bulletin No. 11

MODEL(S): P62
SUBJECT: MODIFIED CYLINDER, P/N 433223
SERIAL NUMBER(S) AFFECTED: 612524738 AND ABOVE

- A number of die changes have recently been completed which will result in an improved service life due to reduced distortion and improved heat dissipation in the cylinder.
- The new cylinder, with its thicker cylinder wall, is easily identified by looking at the 2nd fin from the top...the fin on the new style cylinder is relieved to clear all **four (4)** bolt holes (was 3).

IMPORTANT NOTE: Route the high tension lead (spark plug lead) **above** the cylinder fins for **maximum cooling**.

Old Style



New Style

